DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-001223 Address: 333 Burma Road **Date Inspected:** 19-Dec-2007

City: Oakland, CA 94607

OSM Arrival Time: 1300 **Project Name:** SAS Superstructure **OSM Departure Time:** 2330 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: CWI Present: Yes N/A No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A Yes N/A N/A **Electrode to specification:** No Weld Procedures Followed: Yes No N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:**

34-0006 **Bridge No: Component:** 77, 89, 114 & OBG Mock-Up

Summary of Items Observed:

This Quality Assurance Inspector oversaw Quality Assurance Inspectors Scott Croff and Joe Lanz performing fabrication inspection out on the shop floor today. Mr. Croff performed quality assurance final 10% visual and magnetic particle testing of the 77 Meter Mock-Up Diaphragm after it was returned from machining. Mr. Croff was inspecting the web to web and web to diaphragm welds which he was unable to complete. Mr. Croff did report finding numerous unacceptable visual and magnetic particle indications which were reported in his nightly report. Mr. Lanz was performing visual inspection on the floor beams and visual and magnetic particle testing on the bottom plates for the evening reporting that there were no issues.

Summary of Conversations:

No conversations held today.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mazen Wahbeh, (818) 292-0659, who represents the Office of Structural Materials for your project.

Inspected By: Berger, Bruce Quality Assurance Inspector

Reviewed By: Cochran,Jim **QA** Reviewer